



VIEW C-C

C-10787 Crankshaft Assy. Complete (SAE No. 20 Spline).
Crankshaft similar to C-10839 (has 2-1/2" Crankpins) and
C'bore under Prop Spline has been removed further stiffening shaft.

J Riend 22nov22

NOTE:
These drawings may be used solely for non-commercial use such as historical research,
exhibition, model-making, or for non-profit restoration purposes. Models or restored aircraft
must remain inoperable and incapable of flight. Drawings may not be used to restore operable
aircraft, or engines, to an airworthy status or building flyable or operable reproductions or restorations.